

PCG-V505 Series

Quick Start update

The VAIO® Computer Quick Start incorrectly references USB 2.0 ports on pages 20 and 21. The computer's USB ports are compatible with USB 2.0 devices at full and low speeds only.

Sony apologizes for this error and any inconvenience or misunderstanding this may have caused.